


PLUG, STRAIGHT
STYLE RBE, RDE, RSE, RVE, RWE



DIMENSIONS					
'N' Contacts	A	B	C	D	E
010	1.138	.968	.618	.300	.798
020	1.513	1.343	.993	.675	1.173
030	1.888	1.718	1.368	1.050	1.548
040	2.263	2.093	1.743	1.425	1.923
050	2.638	2.468	2.118	1.800	2.298
060	3.013	2.843	2.493	2.175	2.673
070	3.388	3.218	2.868	2.550	3.048
080	3.763	3.593	3.243	2.925	3.423
090	4.138	3.968	3.618	3.300	3.798
100	4.513	4.343	3.993	3.675	4.173

**REFER TO APPENDIX FOR TERMINATION
 DETAILS, HARDWARE STYLES, POLAR-
 IZATION CHART, MOUNTING STYLES,
 VARIATION CODES, AND PWB PATTERNS**